



Complete Assembly



DETAIL A  
SCALE 1 : 1

PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	Magnet Subassembly	
2	1	Support Subassembly	
3	1	Ram Subassembly	
4	2	RLZ0001	Bracket, Leg Jaw
5	1	RLZ0002	Platform, Fracture
6	1	RLZ0003	Jig, Positioning-Fracture
7	2	ANSI B18.6.3 - 1/4-20 UNC	Hexagon Head Screw
8	2	ANSI B18.3 - 1/4 - 20 UNC	Hexagon Head Screw

DIMENSIONS ARE IN INCHES			AUTHOR	DATE
UNLESS OTHERWISE SPECIFIED, TOLERANCES ARE:			Robert Zondervan	5/3/2018
NO DECIMAL PLACE: +/- 0.50			TITLE	
ONE DECIMAL PLACE: +/- 0.25			Complete Assembly	
TWO DECIMAL PLACE: +/- 0.10			PROJECT	
ANGULAR: +/- 5°			JOVE - Fracture Apparatus Design and Protocol Optimization	
FIGURE		SCALE	SHEET	
S9		1 / 2	9	