

(A)

Step 5 of 5: Start AutoCount

<< Back Start AutoCount

	1	2	3	4	5	6	7	8	9	10	11	12
A	C	C	C	C	C	C	C	C	C	C	C	C
B	C	C	C	C	C	C	C	C	C	C	C	C
C	C	C	C	C	C	C	C	C	C	C	C	C
D	C	C	C	C	C	C	C	C	C	C	C	C
E	C	C	C	C	C	C	C	C	C	C	C	C
F	C	C	C	C	C	C	C	C	C	C	C	C
G	C	C	C	C	C	C	C	C	C	C	C	C
H	C	C	C	C	C	C	C	C	C	C	C	C

Save/Export Well Image Save/Export Group of Wells Print Wizard Export Wizard

EXIT AutoCount

(B)

Quality Control Project

Please select plates to be subjected to quality control.
Select any plate in the list and click on 'Start QC' to begin the quality control process.

Add Plate(s) Add Experiment Add List Search Plates

Plate Name	Status

Remove Selected Plate(s) Remove All Plate(s) SAVE AS NEW LIST

Start QC EXIT QC

Quality Control Project

Please select plates to be subjected to quality control.
Select any plate in the list and click on 'Start QC' to begin the quality control process.

Add Plate(s) Add Experiment Add List Search Plates

Plate Name	Status
D:\Plates\WJE\	counted

Remove Selected Plate(s) Remove All Plate(s) SAVE AS NEW LIST

Start QC EXIT QC